

JC Trail Users

Notes from January 10, 2018 Trail Improvements Hike
Frog Hollow Trail

Recommendations

1. Swooping gully crossing ok, needs armoring, possibly a bridge at the bottom. Erosion must be prevented.
2. Bench could be installed on right just below sweeping turn by unofficial cutoff (the Janeen turn).
3. Need better signs!
4. Finish clearing an alternate line around a rock hump on right on the return trail, halfway between unofficial trail connector and the glade. This will make a small obstacle or jump. Connector sign might as well be put up at cut through.
5. Fix connector trail at glade to reduce runoff.
6. Continue to fix muddy uphill where “flagstones” were set last year.
7. Obtain water if possible at trailhead.
8. Fix gully that is forming at second (maybe 3rd) drainage past the power line cut on the outgoing trail.
9. In the future trail features could be installed near the fence-line to the left of the outgoing trail.
10. Bench could be installed just before the first turn as the outgoing trail starts downhill. There is an old trace of a trail in the woods at this location.
11. Both downhill turns on this part of the outgoing trail need to be repaired.