

# Trail Improvements Hike

November 10, 2019

## Recommendations for Westernmost Loop

- Install a water diversion hump and drain about halfway up the first uphill on the outgoing trail where a turn is starting to erode.
- Saw off a tall tree stub after rocks on the first uphill.
- Install water diversion humps on the last turn before the small field.
- Address the beginning of erosion on the turn before the log pile.
- Fix the abrupt right-hand turn before the bridge on the outgoing trail.
- Install water diversion humps and drains as needed on the first and second turns after the bridge.
- Install another board on the ramp at the top of the last uphill on the outgoing trail.
- Use a digging tool to check the return trail for tripping hazards. See if a couple of them can be removed.

## Items Left from Previous Years

- Work with Parks and Rec to get benches installed at the locations the group selected.
- See about getting a bulletin board installed by the bridge.
- Continue to fix erosion problems on the turns on the first uphill of the outgoing trail. The second turn needs the most work.
- Reroute the first turn past the place where rocks were put in the muddy spot on the outgoing trail.